
DIN W48×H48mm Star-Delta Timer

■ Features

- •Realization of wide range of power supply
- : **24-240VAC 50/60Hz** / 24-240VDC, 12VDC
- •This is upgraded model from AT8SD series.
- •Wide range of setting time and switching time.
 - T1 (Setting time) : Selectable 5, 10, 50, 100sec
 - T2(Switching time) : Selectable 0.05, 0.1, 0.2, 0.3, 0.4, 0.5sec
- Easy setting of time, switching time on front panel.
- •Built-in LED indicator for output status.
- •Application: Starting large capacity motors





Ordering information



Specifications


***A** blacked() item is upgraded function.

Model		AT8SDN			
Function		Star-Delta TIMER			
Control time setting range		0.5sec~100sec(Max. time)			
Power supply		24-240VAC 50/60Hz / 24-240VDC, 12VDC			
Allowable voltage range□		90 ~ 110% of rated voltage□			
Power consumption		Approx. 2.8VA(24-240VAC 60Hz), Approx. 1.3W(24-240VDC), Approx. 0.5W(12VDC			
Return time□		Max. 100ms			
Time operation		Power ON Start type			
Control output□	Contact type	从 contact: SPST(1a), △ contact: SPST(1a)			
	Contact capacity	250VAC 3A resistive load			
Relay	Mechanical	Min.10,000,000 times			
life cycle	Electrical	Min. 100,000 times (250VAC 3A resistive load)			
Repeat error		Max. ±0.3%			
人 Setting error		Max. $\pm 5\% \pm 0.05$ sec.			
Voltage error		Max. ±0.5%			
Temperature error		Max. ±2%			
△ Switching time error		±25%			
Insulation resistance		100MΩ (at 500VDC)			
Dielectric strength		2000VAC 50/60Hz for 1 minute			
Noise strength		±2kV the square wave noise(pulse width:1µs) by the noise simulator			
Vibration	Mechanical	0.75mm amplitude at frequency of 10 ~ 55Hz in each of X, Y, Z directions for 1 hor			
Vibration	Malfunction	0.5mm amplitude at frequency of 10 \sim 55Hz in each of X, Y, Z directions for 10 minutes			
Shock	Mechanical	300m/s² (Approx. 30G) in X, Y, Z directions 3 times			
	Malfunction	100m/s² (Approx. 10G) in X, Y, Z directions 3 times			
Ambient temperature		-10 ~ 55℃ (at non-freezing status)			
Storage temperature		-25 ~ 65℃ (at non-freezing status)			
Ambient humidity		35 ~ 85%RH			
Approval		₂₀ (/ ² 3 ∋)			
Unit weight		Approx. 100g			


B-45 Autonics

Star-Delta Timer


■ Connections



Dimensions



■ Front panel identification



(A) Counter

(B) Timer

(C) Temp. controller

(D) Power controller

(E) Panel meter

(F) Tacho/ Speed/ Pulse meter

(G) Display unit

(H) Sensor controller

(I) Switching power supply

(J) Proximity sensor

(K) Photo electric sensor

(L) Pressure sensor

(M) Rotary encoder

(N) Stepping motor & Driver & Controller

(O) Graphic panel

(P) Production stoppage models & replacement

Autonics B-46

■Time specifications


1. T1 (Setting time)

Time range	Time unit	Time setting range		
0.5		0.5 ~ 5sec		
1.0	×10sec	1 ~ 10sec		
5	^ 105ec	5 ~ 50sec		
10		10 ~ 100sec		

2. T2(Switching time)


(Unit:ms)

Display	Α	F	F1	С	D	I
T2 switching time	50	100	200	300	400	500



Operation

When power is applied, λ contact will be ON. When reaching to T1 setting time, λ contact will be OFF and Δ contact will be ON after switching time of T2 is passed. If the power is OFF, λ contact will be OFF.




※T1: Setting time (★ contact operation time)

*T2: Switching time ($oldsymbol{\wedge}$ contact and $oldsymbol{\Delta}$ contact are OFF simultaneously at power ON)

Proper usage

- 1. Please supply power quickly at once with using switch or relay contact. Otherwise it may cause time error or power reset failure.
- 2. The product life cycle can be shorten by generation of heat when applying an electric current for long hours.
- 3. Please be notice polarity when power is DC power type.
- 4. Please use it like (Fig. 2) in order not to flow leakage current into timer connecting resistance and condenser.



- 5. Do not change setting time(T1), time range, switching time(T2) while time oprating.
- 6. Environment

Please avoid the following places:

- •Where this product may be damaged by strong impact or vibration.
- •Where there are corrosive gas or flammable gas, water, oil and dust.
- •Where magnetic and electrical noise occurs.
- •Where there are High temperature and humidity beyond rated specification.
- •Where there are strong alkalis and acids.
- •Where there are direct rays of sun.

B-47 Autonics